INSPEX IN

INDUSTRIAL X-RAY INSPECTION SOLUTION



NON-DESTRUCTIVE AND VERSATILE INSPECTION

- Incorrect assembly (absence or wrong position of screws, connectors, etc), material failure (cracks, etc), dimensions, foreign bodies
- On pre-assembled and complex systems

SAFE CONTROL

With protection devices to ensure containment of radiation during the control cycle

AUTOMATED OPTIONS

Loading and unloading of parts, camera angles, sorting and marking, etc

PERFORMANCE	
Imaging system*	1000x1000 pixels CCD camera
	Up to 30 frames per second
	Focal length 30 mm +/- 1%
	Aperture F/2 to F/12
Measurement uncertainty – dimension*	Up to 0.2mm
Cycle time*	Less than 15 seconds
GENERAL	
Dimensions in mm* (H / D / L)	3110 / 2220 (closed) to 2830 (open) / 3300

^{*}Typical values, can be tailored to your control requirements